

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20160808-E484880  
**Report Reference** E484880-20160808  
**Issue Date** 2016-AUGUST-08

**Issued to:** TIANJIN GENEVO TECHNOLOGY CO LTD  
Technology Av., South Economic Development Area  
Tianjin, 301609 CHINA

**This is to certify that representative samples of** COMMUNICATIONS AUDIO/VIDEO DATA AND OTHER SIGNALING-CIRCUIT ACCESSORIES  
RJ45 Patch Cord, Models RJ45S, M/F41, and RJ45S-2M/F41

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL 1863, Standard for Safety for Communication Accessories,  
CSA C22.2 No. 182.4-M90, Standard for Plugs, Receptacles and Connectors for Communication Systems,  
CSA C22.2 No. 233-09, Standard for Cords and Cord Sets for Communication Systems

**Additional Information:** See the UL Online Certifications Directory at [www.ul.com/certifications](http://www.ul.com/certifications) for additional information.

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Program.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information or services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/customer-service>

